



NOTE: FOR 110V NO METER SHUNT IS REQUIRED.
THE AMMETER BEING DIRECT READING AND
CONNECTED IN PLACE OF THE SHUNT



ALL DEVICES ARE SHOWN IN A
DE ENERGISED, RESET OR SHUT
DOWN CONDITION WITH ALL
HYDRAULIC SYSTEMS DRAINED
AND AT ATMOSPHERIC
PRESSURE

DATE: 21-3-73
DRAWN: MC
CHECKED: *[Signature]*
APPROVED: *[Signature]*

QUIRK'S VICTORY LIGHT
CO.
CIRCUIT DIAGRAM
Brushless Kind Plant, 2 kw.

UNSPECIFIED TOLERANCES
INCH METRIC
Mach Decimals ±0.005 ±0.125mm
Mach Fractions ±1/16 ±1.5mm
FRACTIONS ±1/16 ±1.5mm
SHEET 1 OF 2
A3 102173-1 A